

ONLINE AUTOMOTIVE SERVICE INFORMATION  
FOR JULY 2014

**SB-10057740-2019**

44643 2015 Lincoln MKC - Power Steering Control Module (PSCM) - False DTC U0159

Some 2015 Lincoln MKC vehicles equipped with active park assist may generate a false DTC U0159 for the Power Steering Control Module (PSCM) during delivery of the vehicle at the dealership. This DTC has no impact on the function of the active park assist or steering system. Do not perform any service actions for PSCM U0159 unless the following is present: 1) A DTC is present in the Park Assist Module (PAM). 2) The scan tool indicates the PAM is not responding. 3) The customer reports an issue with the park assist function. If any of the above are true refer to Section 413-13C of the Workshop manual to resolve the DTC/issue with the PAM. Once the DTC/issue with the PAM has been resolved clear codes in the PSCM and verify the U0159 is no longer present. If it is still present, refer to WSM section 211-02 for diagnostics.