

ONLINE AUTOMOTIVE SERVICE INFORMATION SYSTEM  
FOR SEPTEMBER 2014

**SB-10057743-7872**

44737 2015 MKC - Disregard U0415 In Power Steering Control Module (PSCM) If No Power Steering Concern Is Present

Some 2015 MKC vehicles may exhibit a U0415 DTC in the Power Steering Control Module (PSCM) that clears, but may return after a short time. This code is a commonly set DTC in the PSCM and can be disregarded unless there is a customer complaint that is specifically related to the Electronic Power Assist Steering (EPAS) system.