

ONLINE AUTOMOTIVE SERVICE INFORMATION SYSTEM
FOR SEPTEMBER 2014

SB-10057860-9313

44733 2009-2010 Escape, Mariner And 2010 Fusion, Milan Vehicles With DTC's P0735

Some 2009-2010 Escape, Mariner, and 2010 Fusion, Milan vehicles may have Diagnostic Trouble code (DTC) P0735 stored as a result of a worn Solenoid Pressure Regulator valve bore in the valve body (Balloon # 7 in the Work Shop Manual valve body exploded view). If this DTC is encountered and OASIS repair history indicates the valve body has not previously been replaced. Replace valve body using WSM and available service labor times. If valve body was replaced follow normal WSM Diagnostic for DTC P0735 in section 307-01. If diagnostic leads you back to valve body here how to identify bore wear. Clean the valve and bore with solvent and then dry completely before inspection. Then inspect for a loose valve in the bore or the valve body bore surface scored on one side of the bore.