

## **SB-10057863-3997**

### ONLINE AUTOMOTIVE SERVICE INFORMATION SYSTEM FOR SEPTEMBER 2014

44701 2013-2015 Fusion/MKZ - Disregard U0415 In Power Steering Control Module (PSCM) If No Power Steering Concern Is Present

Some 2013-2015 Fusion/MKZ vehicles may exhibit a U0415 DTC in the Power Steering Control Module (PSCM) that clears, but may return after a short time. This code is a commonly set DTC in the PSCM and can be disregarded unless there is a customer complaint that is specifically related to the Electronic Power Assist Steering (EPAS) system.