

ONLINE AUTOMOTIVE SERVICE INFORMATION SYSTEM
FOR SEPTEMBER 2014

SB-10057869-8011

44717 2013-2014 Fusions Built At FlatRock Assembly Plant - Headliner Sag In Various Locations

Some 2013-2014 Fusion vehicles built at the Flatrock Assembly Plant may exhibit various headliner concerns such as a sag of the headliner at the center high mounted stop lamp, sag at one or more door opening, or a sag around the roof opening panel. Unless the headliner is obstructing the driver's view or passenger comfort, do not replace the headliner at this time. Engineering is currently investigating this concern. Continue to monitor Oasis for further repair direction.
