



Mercedes-Benz

The best or nothing.

star bulletin



Date: March 10, 2014
Order No.: P-B-82.85/703
Group: 82

SUBJECT: MY-All Models 204.0/2/9 with CODE 512 (COMAND Online); with CODE 800 (Model year 2010); without CODE 088 (Control code NTG 4.5)
MODEL 204.0/2/9 with CODE 512 (COMAND Online); with CODE 801 (Model year 2011); without CODE 088 (Control code NTG 4.5)
MODEL 204.0/2/9 with CODE 512 (COMAND Online); with CODE 808 (Model year 2008); without CODE 088 (Control code NTG 4.5)
MODEL 204.0/2/9 with CODE 512 (COMAND Online); with CODE 809 (Model year 2009); without CODE 088 (Control code NTG 4.5)
MODEL 204.0/2/9 with CODE 527 (COMAND Online); with CODE 800 (Model year 2010); without CODE 088 (Control code NTG 4.5)
MODEL 204.0/2/9 with CODE 527 (COMAND Online); with CODE 801 (Model year 2011); without CODE 088 (Control code NTG 4.5)
MODEL 204.0/2/9 with CODE 527 (COMAND Online); with CODE 808 (Model year 2008); without CODE 088 (Control code NTG 4.5)
MODEL 204.0/2/9 with CODE 527 (COMAND Online); with CODE 809 (Model year 2009); without CODE 088 (Control code NTG 4.5)
MODEL 204 with CODE 511 (Audio 50 APS incl. DVD changer and LINGUATRONIC); with CODE 800 (Model year 2010)
MODEL 204 with CODE 511 (Audio 50 APS incl. DVD changer and LINGUATRONIC); with CODE 801 (Model year 2011)
MODEL 204 with CODE 511 (Audio 50 APS incl. DVD changer and LINGUATRONIC); with CODE 802 (Model year 2012)
MODEL 204 with CODE 511 (Audio 50 APS incl. DVD changer and LINGUATRONIC); with CODE 808 (Model year 2008)
MODEL 204 with CODE 511 (Audio 50 APS incl. DVD changer and LINGUATRONIC); with CODE 809 (Model year 2009)
MODEL 204 with CODE 525 (Audio 50 APS); with CODE 800 (Model year 2010)
MODEL 204 with CODE 525 (Audio 50 APS); with CODE 801 (Model year 2011)
MODEL 204 with CODE 525 (Audio 50 APS); with CODE 802 (Model year 2012)
MODEL 204 with CODE 525 (Audio 50 APS); with CODE 808 (Model year 2008)
MODEL 204 with CODE 525 (Audio 50 APS); with CODE 809 (Model year 2009)

Telematics DVD

This bulletin has been created and maintained in accordance with MBUSA-SLP S423QH001, Document and Data Control, and MBUSA-SLP S424HH001, Control of Quality Records.

© 2014 Mercedes-Benz USA, LLC.
Mercedes-Benz Canada, Inc.
Dealer Workshop Services
www.MBUSA.com
www.startekinfo.com

All rights reserved. Reproduction or translation in whole or in part is not permitted without authorization from the publisher. Printed in U.S.A.
1-800-FOR-MERCEDES

A production fault means that the telematics DVD A 166 827 14 00 cannot be used. Because of this the previous telematics DVDs A 204 827 03 65 and A 204 827 10 65 must continue to be used for control unit programming. If required, these are still available for ordering. With XENTRY DVD 03/2014 a new telematics DVD with part number A 166 827 21 00 is being shipped. This telematics DVD replaces the previous telematics DVDs.