

	GROUP Body	MODEL 2014MY Sportage (SL)
	NUMBER PS290	DATE January 2014
 		
SUBJECT: SUCTION CUP RESIDUE ON WINDSHIELD		

Residue from installation of the windshield may cause four markings in the shape of suction cups to appear on the surface of the windshield, as shown below. This condition is more apparent when condensation occurs on the windshield and the moisture evaporates at different rates, leaving behind visible rings. In order to verify this condition, spray rubbing alcohol over the surface of the windshield at the approximate locations in the image below. Wipe the surface with a cloth and inspect for the presence of the markings. If the markings are evident, continue spraying rubbing alcohol over the marking(s) and wiping with the cloth until all residue is removed from the windshield.

