



TECH TIP: Passenger seat not as warm as the driver's seat

NUMBER: TT046

MODEL: 2011-13MY Sorento (XMa)

DATE: 01/17/2014

Symptom: Some customers may complain that the passenger front seat heater does not get as warm as the driver's seat.

Repair: There will be a difference in temperature between the RH and LH cushions. The same heaters are used in the cushions of both seats, but the RH cushion has a body sensor mat applied over the heater, resulting in less heat reaching the front passenger.

Note: Tech Tips are not a substitute for proper diagnosis.