



TECH TIP: Navigation System Displaying the Wrong Location

NUMBER: TT057

MODEL: 2014MY Cadenza (VG)

DATE: 04/01/2014

Symptom: Customer complains that the location displayed on the map is different than the actual location (i.e. system shows location in a river, lake, etc.).

Repair: Check for bent pins at connector FR11 (34-WHT) located in the left front A-pillar (click on images).



Note: Tech Tips are not a substitute for proper diagnosis.