



TECH TIP: HVAC Blower Stuck on High

NUMBER: TT060

MODEL: 2011 > Optima (QF)

DATE: 04/01/2014

Symptom: HVAC blower stuck on high speed only.



Repair: Check connector EM61 - Pin 41 (Yellow wire) for a loose connection (see diagram). Connector EM61 is located in the right kick panel under the right side A-Pillar. Repair pin 41 to ensure proper contact and operate the blower controls to make sure proper function is restored.

Note: Tech Tips are not a substitute for proper diagnosis.