



**HYUNDAI** | NEW THINKING.  
NEW POSSIBILITIES.

**Technical Service Bulletin**

GROUP	NUMBER
DRIVESHAFT AND AXLE	14-DS-001-1
DATE	MODEL(S)
APRIL 2014	SONATA (YF)

**SUBJECT:** YF SONATA JOINT AND SHAFT KIT AVAILABILITY

**THIS TSB SUPERSEDES TSB 14-DS-001 TO UPDATE CAUSAL PART NUMBERS.**

**Description:**

It is not necessary to replace the complete driveshaft assembly when servicing the driveshaft or CV joint. Instead, replace the appropriate wheel side joint and shaft kit. Refer to the repair procedure located in the applicable Service Shop Manual: Driveshaft and Axle → Front Driveshaft → Repair Procedures section.



**Applicable Vehicles:** 2011MY~2014MY Sonata (YF) 2.0T / 2.4L

**Parts Information:**

Model	Comment	Part Name	Part Number	Quantity
Sonata (YF)	2.4L w/ Automatic Transmission	Wheel Side Joint and Shaft Kit LH	10232-979	1
		Wheel Side Joint and Shaft Kit RH	10251-072	

Circulate To: General Manager, Service Manager, Parts Manager, Warranty Manager, Service Advisors, Technicians, Body Shop Manager, Fleet Repair

**SUBJECT:**

YF SONATA JOINT AND SHAFT KIT AVAILABILITY

Model	Comment	Part Name	Part Number	Quantity
Sonata (YF)	2.4L w/ Manual Transmission	Wheel Side Joint and Shaft Kit LH	49580-3S000	1
		Wheel Side Joint and Shaft Kit RH	49580-3S070	
	2.0T w/ Automatic Transmission	Wheel Side Joint and Shaft Kit LH	49580-3Q700	
		Wheel Side Joint and Shaft Kit RH	49580-3Q750	

**Warranty Information:**

Model	Op Code	Operation	Op Time	Causal Part #	Nature Code	Cause Code	
Sonata (YF)	49507R0B	Joint and Shaft Kit (Both Sides)	1.5	2.4 AT	N29	C11	
				2.4 MT			10232-979 (LH) 10251-072 (RH)
				2.0T AT			49580-3S000 (LH) 49580-3S070 (RH)
	49507R0R	Joint and Shaft Kit (RH)	1.0	2.4 AT			10251-072 (RH)
				2.4 MT			49580-3S070 (RH)
				2.0T AT			49580-3Q750 (RH)
	49507R00	Joint and Shaft Kit (LH)	1.0	2.4 AT			10232-979 (LH)
				2.4 MT			49580-3S000 (LH)
				2.0T AT			49580-3Q700 (LH)