



S-SB-0012-14


April 29, 2014

HVAC Evaporator Drain Hose Clogged Due to Insect Intrusion

Service Category Vehicle Interior

Section Heating/Air Conditioning

Market USA



Applicability

YEAR(S)	MODEL(S)	ADDITIONAL INFORMATION
2011 – 2014	tC	
2008 – 2014	xB	
2008 – 2014	xD	

Introduction

Some vehicles in particular geographic areas may exhibit a condition where the HVAC Evaporator Drain Hose has become obstructed with an insect nest. An insect repellent drain hose tip (ARINIX[®] Tip) is now available to help minimize future occurrences of this environmental condition. For some models, a new drain hose is required to properly fit the ARINIX[®] Tip. Follow the procedures in this bulletin for proper handling and installation of this optional service part.

NOTE
 The ARINIX[®] Tip is NOT registered or labeled for sale or use outside the United States or Puerto Rico.

Warranty Information

OP CODE	DESCRIPTION	TIME	OFFP	T1	T2
N/A	Not Applicable to Warranty	–	–	–	–

HVAC Evaporator Drain Hose Clogged Due to Insect Intrusion

Parts Information

MODEL	MODEL YEAR	PART NUMBER		PART NAME	REPAIR PROCEDURE	QTY
		PREVIOUS	NEW			
All	2008 – 2014	87265-33010		Connector, Water Hose (ARINIX® Tip)	All	1
tC	2011 – 2013	88539-12200	88539-12230	Hose, Drain Cooler	A	1
			90480-26030	Grommet		1
	Late 2013 – 2014	88539-21030		Hose, Drain Cooler	B	1
xB	2008 – 2013	88539-12200	88539-12230	Grommet	A	1
			90480-26030			1
	2014	88539-12230		Hose, Drain Cooler	B	1
xD	2008 – 2010	88539-52020		Hose, Drain Cooler	B	1
	2011 – 2014	88539-52040				1

Required Tools & Equipment

REQUIRED MATERIAL	QUANTITY
Chemical Resistant Gloves (Made From Waterproof Material)	1

Safety Requirements for Handling the ARINIX® Tip (Connector, Water Hose)

- Follow the manufacturer's instructions for cleaning/maintaining Personal Protection Equipment (PPE). If no such instructions for cleaning/maintaining PPE exist, use detergent and hot water. Keep PPE separate from other laundry.
- Users should remove PPE immediately after handling this product.
- Wash the outside of the gloves before removing.
- Users should wash hands before eating, drinking, chewing gum, or using the toilet.

HVAC Evaporator Drain Hose Clogged Due to Insect Intrusion

Safety Requirements for Handling the ARINIX® Tip (Connector, Water Hose) (Continued)

CAUTION**IF SWALLOWED:**

Call the poison control center or doctor immediately for treatment advice. Have the person sip a glass of water if able to swallow.

- Do NOT induce vomiting unless instructed by the poison control center or doctor.
- Do NOT give anything by mouth to an unconscious person.

IF ON SKIN OR CLOTHING:

Take off the contaminated clothing immediately. Rinse skin immediately with plenty of water for 15 to 20 minutes. Call a poison control center or doctor for treatment advice.

IF IN EYES:

Hold eye open and rinse gently and slowly with water for 15 to 20 minutes. Remove contact lenses (if present) after the first 5 minutes, then continue rinsing eye. Call poison control center or doctor for treatment advice.

HOTLINE NUMBER:

Have the product container or label with you when calling a poison control center, doctor, or going for treatment. You may also contact 800-424-9300 for emergency medical treatment information.

HVAC Evaporator Drain Hose Clogged Due to Insect Intrusion

Directions for Use on ALL Repair Procedures

The ARINIX[®] Tip contains permethrin, a pesticide, as the active ingredient. Please note, it is a violation of Federal law to use this product in a manner inconsistent with its labeling.

Repair Procedure A

1. Follow the instructions provided in the Safety Requirements for Handling the ARINIX[®] Tip (Connector, Water Hose) section of this bulletin.
2. Locate the HVAC Evaporator Drain Hose.
3. Following the vehicle specific Repair Manual, remove the HVAC Evaporator Drain Hose.
4. Put on all necessary PPE and install the ARINIX[®] Tip (Connector, Water Hose) into the NEW HVAC Evaporator Drain Hose listed in the Parts Information section of this bulletin.
5. When installing the ARINIX[®] Tip, verify it is fully seated in the HVAC Evaporator Drain Hose as shown in Figure 1.
6. Following the vehicle specific Repair Manual, install the HVAC Evaporator Drain Hose.

Figure 1.



HVAC Evaporator Drain Hose Clogged Due to Insect Intrusion

Repair Procedure B

1. Follow the instructions provided in the Safety Requirements for Handling the ARINIX[®] Tip (Connector, Water Hose) section of this bulletin.
2. Locate the HVAC Evaporator Drain Hose.
3. Following the vehicle specific Repair Manual, remove the HVAC Evaporator Drain Hose.
4. Put on all necessary PPE and install the ARINIX[®] Tip into the original HVAC Evaporator Drain Hose listed in the Parts Information section of this bulletin.
5. When installing the ARINIX[®] Tip, verify it is fully seated in the HVAC Evaporator Drain Hose as shown in Figure 1.
6. Following the vehicle specific Repair Manual, install the HVAC Evaporator Drain Hose.