



HYUNDAI | NEW THINKING.
NEW POSSIBILITIES.

TECHNICAL SERVICE BULLETIN

GROUP BODY ELECTRICAL	NUMBER 14-BE-009
DATE JUNE, 2014	MODEL(S) SONATA (LF)

SUBJECT: BLUE LINK: TELEMATICS UNIT LOCATION

DESCRIPTION: This bulletin provides information to assist in locating the Telematic Unit for the 15 MY Sonata (LF). Please refer to the shop manual for more information on unit replacement procedures and connector pin out information.

Applicable Vehicles: 2015 Sonata (LF) equipped with Blue Link

NAVIGATION SYSTEM: TELEMATIC UNIT LOCATION




The TMU (Telematics Unit) is integrated inside the head unit. If TMU replacement is necessary, the entire head unit will need to be replaced.

CAUTION

- Never replace with a used head unit.
- Never swap the head units between vehicles. NOT even for testing purposes only.

Circulate To: General Manager, Service Manager, Parts Manager, Warranty Manager, Service Advisors, Technicians, Body Shop Manager, Fleet Repair

STANDARD AUDIO SYSTEM: TELEMATIC UNIT LOCATION



The TMU (Telematics Unit) is external to the head unit. Replacement of the TMU/TMS will require replacement of the Blue Link Unit (Item #9).

CAUTION

- Never replace with a used Blue Link TMU.
- Never swap the Blue Link TMU between vehicles. NOT even for testing purposes only.