
From: gm_gmssg_q01 <nobody@gm.com>
Sent: Tuesday, April 01, 2014 2:00 PM
To:
Subject: Internal notification for: G_0000188928 14079A - Safety Recall - Stop Delivery Until Safety Recall Has Been Performed on the Vehicle - Revised
Attachments: 14079A bulletin.pdf

Date: 4/01/2014 Ref. number: Service / Field Action / G_0000188928
Subject: **14079A - Safety Recall - Stop Delivery Until Safety Recall Has Been Performed on the Vehicle - Revised**

**GM CUSTOMER CARE AND AFTERSALES
DCS3176
URGENT - DISTRIBUTE IMMEDIATELY**

Date: April 1, 2014

Subject: 14079A - Safety Recall – Stop Delivery Until Safety Recall Has Been Performed on Vehicle - Revised
Front Axle Right Half Shaft Fracture

Models: 2013-2014 Chevrolet Cruze Equipped with 1.4L Turbo Engine (LUV)


To: All Chevrolet Dealers

Attention: General Manager, Service Advisor, Service Manager, Parts and Service Director, Parts Manager, New Vehicle Sales Manager, Used New Vehicle Sales Manager, and Warranty Administrator

The part numbers for the half shaft have been revised in bulletin 14079A. Please discard all copies of bulletin 14079.

**END OF MESSAGE
GM CUSTOMER CARE AND AFTERSALES**

Message Attachment(s):

 [14079A bulletin.pdf](#) Acrobat PDF (293.3KB)
14079A bulletin

Contact name: E-Mail:
Department: Service - Brand Quality Phone:
Intended roles: General Manager, New Vehicle Sales Manager, Parts & Service Director, Parts Manager, Service Advisor, Systems Manager, Used Vehicle Sales Manager, Warranty Administrator