
From: gm_gmssg_q01 <nobody@gm.com>
Sent: Monday, March 31, 2014 11:09 PM
To:
Subject: Internal notification for: G_0000188789 14121A - Safety Recall - Transmission Oil Cooler Connection - Revised
Attachments: 14121A bulletin.pdf

Date: 3/31/2014 Ref. number: Service / Field Action / G_0000188789
Subject: **14121A - Safety Recall - Transmission Oil Cooler Connection - Revised**

**GM CUSTOMER CARE AND AFTERSALES
DCS3174
URGENT - DISTRIBUTE IMMEDIATELY**

Date: March 31, 2014

Subject: 14121A – Safety Recall
Transmission Oil Cooler Connection
Revised Part Information

Models: 2014 Chevrolet Silverado Light Duty Regular Cab, Double Cab,
Crew Cab 1500 Series
2015 Chevrolet Suburban, Tahoe
2014 GMC Sierra Light Duty Regular Cab, Double Cab, Crew
Cab 1500 Series
2015 GMC Yukon, Yukon XL
Equipped with 6-Speed Automatic Transmission (MYC)

To: All Chevrolet and GMC Dealers

Attention: General Manager, Service Advisor, Service Manager, Parts and
Service Director, Parts Manager, New Vehicle Sales Manager,
and Warranty Administrator

The part description for part number 23135704 has been revised and a Note statement before Step 2.4 has been added. Please discard all copies of bulletin 14121.

**END OF MESSAGE
GM CUSTOMER CARE AND AFTERSALES**