



# Service Bulletin

File in Section: -

Bulletin No.: PIP5188

Date: June, 2014

## PRELIMINARY INFORMATION

**Subject:** Diagnostic Tips For Raw Fuel In The EVAP Canister

**Models:** 2014 Chevrolet Corvette  
Equipped with engine RPO LT1 6.2L

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

### Condition/Concern

A vehicle may have a concern of a fuel odor from the rear of the vehicle and or rich codes.

You may find the EVAP canister is full of raw fuel.

This concern may be caused by more than force filling the fuel tank.

### Recommendation/Instructions


If this is encountered there are some connections in the fuel tank that should be inspected.

Below are pictures of location to check for the concern



This connection is in the left fuel tank

3752902



3752898

These connection are in the right side fuel tank

Note the connections at the crossover pipe are not super easy to detect.

### **Warranty Information**

The correction for this concern may be one of several repairs described above. For vehicles repaired under warranty, please use the appropriate warranty labor operation based on the actual cause and repair.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.