



Service Bulletin

File in Section: -

Bulletin No.: PI1167

Date: February, 2014

PRELIMINARY INFORMATION

Subject: Missing Nut on Stud for 100 Amp Fuse

Models: 2014 Chevrolet Corvette

Condition/Concern



3705136

The purpose of the PI is to inform the customer and dealership personnel that the stud for the 100 amp fuse does not require a nut as shown in the illustration above. This fuse block is a common part and the Corvette does not use the 100 amp fuse.

Note: DO NOT order a nut for the 100 amp fuse.