



Service Bulletin

File in Section: -

Bulletin No.: PIT5274

Date: April, 2014

PRELIMINARY INFORMATION


Subject: Roof Beacon Lighting Harness Location

Models: 2015 Chevrolet Silverado
2014 Chevrolet Silverado 1500
2015 GMC Sierra
2014 GMC Sierra 1500
With Roof Lamp / Beacon Wiring Provisions (RPO TRW) or Snow Plow Prep Package (RPO VYU)

Some owners may question where the blunt cut wires are located for the roof beacon light.

There are two wires located directly above the overhead roof console. Remove the complete overhead roof console and the wires are taped to the harness, as shown below.

Note: The roof beacon relay is located directly above the overhead roof console.



3794424