



Service Bulletin

File in Section: -

Bulletin No.: PI1312

Date: September, 2014

PRELIMINARY INFORMATION


Subject: A/C Compressor and A/C Pipe Assembly Changes

Models: 2015 Chevrolet Equinox (Built Prior to VIN Breakpoint F6126358)
2015 GMC Terrain (Built Prior to VIN Breakpoint F6127049)
Equipped with 3.6L Engine (RPO LFX)

Condition/Concern

The purpose of this PI is to inform dealership personnel and technicians of a design and supplier change with the A/C compressor. Please use the following information below to identify the design changes.


2010-2014 Model Year A/C Compressor and Pipe Assembly Design



3968746

The 2010-2014 A/C compressor and pipe assembly design will have a smaller label on the compressor located near the pulley (1). The location where the A/C pipe housing mounts to the compressor is rectangular (2) and the connector bracket for the compressor harness is horizontal and located on the bottom rear of the compressor (3).

2015 Model Year A/C Compressor and Pipe Assembly Design Changes



3968758

The design changes made for the 2015 model year A/C compressor and pipe assembly consist of a larger label located in the middle of the compressor (1). The A/C pipe housing has a different shape (2) and the connector for the compressor is mounted vertically (3).