



# Service Bulletin

File in Section: -

Bulletin No.: PIC5266A

Date: February, 2014

## PRELIMINARY INFORMATION

**Subject:** Speed Advisory Message Not Displaying On DIC

**Models:** 2009 - 2011 Cadillac DTS  
With Radio (RPO U3R) Without Cruise (RPO K59)

**This PI was superseded to update model years and keywords. Please discard PIC5266.**

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

### Condition/Concern

A customer may comment that the Speed Advisory message does not display on the DIC.

### Recommendation/Instructions

If the customer has a Cadillac DTS built with a U3R Radio but without K59 cruise, and the Speed Advisory message does not display on the DIC, do NOT replace any parts for this concern.

### ADDITIONAL SI KEYWORDS:

alert navigation menu personalization warning

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.