



# Service Bulletin

File in Section: -

Bulletin No.: PIC5790A

Date: April, 2014

## PRELIMINARY INFORMATION

**Subject:** Creak Noise From The Left Front Of The Vehicle When Turning Right

**Models:** 2013 - 2014 Cadillac ATS

**This PI was superseded to update model list. Please discard PIC5790.**

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

### Condition/Concern

A creak noise may be heard in the left front of the vehicle when making hard right turns or fast sweeping turns such as entering/exiting highways. This noise could be difficult to isolate the source.

### Recommendation/Instructions

Inspect the AC Muffler, which is part of the Air Conditioning Compressor and Condenser Hose, for being too close to or possibly contacting any surrounding objects. Reposition the AC Muffler pipe as necessary to eliminate the potential for contact.

### Warranty Information

The correction for this concern may be one of several repairs described above. For vehicles repaired under warranty, please use the appropriate warranty labor operation based on the original cause in addition to well documented straight time.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.