



# Service Bulletin

File in Section: -

Bulletin No.: PIC6043

Date: November, 2014

## PRELIMINARY INFORMATION

**Subject:** No GPS Signal Displayed or Navigation System Does Not Recognize Location of Vehicle

**Models:** 2015 Chevrolet Corvette  
Equipped with Vehicle Performance Data System (RPO UQT)

### Condition/Concern

Some customers may comment that the navigation system does not recognize the location of the vehicle. The customer may notice there is no GPS symbol displayed on the center stack display screen. This may be due to the frontview camera coax cable being pinched by the courtesy lamp harness from the windshield upper garnish molding.

### Recommendation/Instructions

Please contact GM Technical Assistance for further diagnostics