

1OK Fluid or Grease on Caliper.pdf

Reference	SSM71258
Models	LR4 / L319
Title	Front Brake Calliper Appears To Leak Brake Fluid
Category	Chassis
Last modified	06-Feb-2014 00:00:00
Symptom	301000 Service Brake System
Content	<p><u>Issue:</u> Front brake callipers appear to be leaking brake fluid.</p> <p><u>Cause:</u> Assembly grease/fluid is present from the manufacturing process and gives a similar appearance to a brake fluid leak.</p> <p><u>Action:</u> When investigating any potential brake fluid leaks please first remove any traces of grease/fluid from the calliper area then firmly pump the brake pedal several times before re-inspecting to confirm if there is a genuine leak or not.</p> <p>The attached photo shows typical grease/assembly fluid migration over time and is not a leak, this unit has been removed and confirmed as not leaking.</p>

