



ABOVE & BEYOND

UPDATE PRIOR TO SALE UPS9114-1B: ACCELERATOR PEDAL DEFECTIVE SWITCH

SERVICE BULLETIN

08-DEC-14 | No.: SGI14-51 | SECTION: GENERAL INFORMATION | MARKET: CAN / USA

UPS9114-1B SUPERSEDES UPS8514-1B WITH IMMEDIATE EFFECT

DESCRIPTION

A potential issue has been identified on a small number of 2015 model year Range Rover Sport (L494) and Range Rover (L405) vehicles where the accelerator pedal switch printed circuit board may not have been correctly soldered, leading to an intermittent connection. This may result in the vehicle entering restricted performance mode.

AFFECTED VEHICLES

Certain vehicles within the following VIN ranges are affected:

- Range Rover Sport (L494) (LW) 504511-510214; (LW) 601763-604514
- Range Rover (L405) (LG) 197042-203357

ACTION TO BE TAKEN

Retailers are required to **HOLD** only affected vehicles that are within your control and refrain from releasing the vehicles for new or used vehicle sale pending completion of the inspection procedure detailed in this Technical Bulletin. Vehicles which pass this inspection may be released for sale; vehicles which do not pass must be held pending further repair instruction. Details of this repair instruction will be published as soon as possible. Unsold vehicles should have this performed as part of the Pre-Delivery Inspection (PDI) process but must have it completed prior to vehicle handover to the customer.

Affected vehicles already in the hands of customers should be updated at the next available opportunity.

Refer to Technical Bulletin Q442 UPS9114-1bNAS1, *Accelerator Pedal Defective Switch*, for detailed repair instructions.

PARTS

No parts required

TOOLS

Refer to Service Instruction / Repair Procedure for any required tools

WARRANTY

NOTE: check DDW to ensure that the vehicle is affected by this program prior to undertaking any rework action.

Repair procedures are under constant review, and therefore times / prices are subject to change; those quoted here must be taken as guidance only. Refer to TOPIx to obtain the latest repair time. At the time of confirming a booking for vehicle repair, ensure that all outstanding Service Actions are identified to ensure the correct parts are available and adequate workshop time is allocated for repairs to be completed at one visit.

Warranty claims must be submitted quoting Program Code 'Q442' together with the relevant Option Code from the table. SRO and parts information is included for information only. The Option Code(s) that allows for the drive in / drive out allowance may only be claimed if the vehicle is brought into the workshop for this action alone to be undertaken.

Warranty claims must be submitted for payment within 30 calendar days of completion of the repair.

PROGRAM CODE	OPTION CODE	DESCRIPTION	SRO	TIME (HOURS)	PART No. / SUNDRY CODE	QTY. / VALUE
Q442	A	Check the accelerator pedal serial number - no further action	05.10.10	0.10	-	-
Q442	K	Check the accelerator pedal serial number - no further action	05.10.10	0.10	-	-
		Drive in/drive out	02.02.02	0.20	-	-

Normal Warranty policies and procedures apply

UPS8514-1B: AFFECTED VIN LIST

CANADA

VIN	RETAILER No / NAME	VIN	RETAILER No / NAME
FA198654	0502 Land Rover Edmonton	FA505740	0528 Land Rover Halifax
FA197124	0503 Budds' Imported Cars	FA504563	0529 Land Rover Ottawa
FA504760	0503 Budds' Imported Cars	FA504707	0529 Land Rover Ottawa
FA504878	0503 Budds' Imported Cars	FA504973	0529 Land Rover Ottawa
FA505056	0503 Budds' Imported Cars	FA504564	0530 Land Rover Quebec
FA505522	0503 Budds' Imported Cars	FA504640	0530 Land Rover Quebec
FA504665	0509 Decarie Motors, Inc.	FA504598	0531 Land Rover Brossard
FA504961	0509 Decarie Motors, Inc.	FA504943	0531 Land Rover Brossard
FA505071	0509 Decarie Motors, Inc.	FA505066	0531 Land Rover Brossard
FA197221	0519 Land Rover Richmond	FA506199	0535 Coventry North Land Rover
FA504896	0519 Land Rover Richmond	FA198343	0540 Land Rover Calgary
FA505870	0519 Land Rover Richmond	FA505060	0540 Land Rover Calgary
FA506076	0519 Land Rover Richmond	FA505533	0542 Land Rover Laval
FA506306	0520 Land Rover Newfoundland	FA504666	0543 Land Rover Toronto
FA506266	0525 Land Rover Windsor	FA504922	0543 Land Rover Toronto
FA198476	0526 Land Rover Thornhill	FA506258	0544 Land Rover Vancouver
FA504789	0526 Land Rover Thornhill	FA506287	0544 Land Rover Vancouver
FA506030	0526 Land Rover Thornhill	FA506324	0548 Land Rover Waterloo

USA

VIN	RETAILER No / NAME	VIN	RETAILER No / NAME
FA197705	0114 Land Rover Buckhead	FA197296	0320 Land Rover West Columbia
FA197970	0114 Land Rover Buckhead	FA197819	0328 Land Rover Gulf Coast
FA197383	0117 Land Rover Birmingham	FA197887	0330 Land Rover Houston Central
FA197778	0126 Dimmitt Land Rover	FA197921	0336 Land Rover Fort Myers
FA197670	0131 Land Rover North Dade	FA504615	0336 Land Rover Fort Myers
FA504706	0131 Land Rover North Dade	FA197099	0342 Land Rover Fort Lauderdale
FA197844	0136 Land Rover Dallas	FA197129	0342 Land Rover Fort Lauderdale
FA505022	0139 Bob Moore Land Rover	FA504762	0342 Land Rover Fort Lauderdale
FA197294	0143 Land Rover Charlotte	FA505021	0342 Land Rover Fort Lauderdale
FA505036	0143 Land Rover Charlotte	FA197081	0344 Land Rover Houston North
FA197940	0171 Land Rover West Ashley	FA197193	0344 Land Rover Houston North
FA505024	0173 Land Rover Cary	FA197715	0344 Land Rover Houston North
FA197522	0177 Land Rover Orlando	FA504807	0348 Land Rover Hilton Head
FA197104	0187 Land Rover Birmingham	FA197117	0355 Land Rover North Hills
FA197859	0205 Land Rover Ft. Worth	FA197072	0359 Land Rover Southwest Houston
FA198076	0205 Land Rover Ft. Worth	FA197260	0359 Land Rover Southwest Houston
FA197486	0228 Land Rover Tampa	FA197114	0371 Land Rover Little Rock
FA197206	0230 Land Rover Grand Rapids	FA197186	0389 Land Rover Treasure Coast
FA197108	0233 Land Rover Greensboro	FA504913	0389 Land Rover Treasure Coast
FA197239	0234 Land Rover Austin	FA504957	0389 Land Rover Treasure Coast
FA198247	0234 Land Rover Austin	FA197495	0391 Land Rover Palm Beach
FA505051	0238 Land Rover Knoxville	FA197689	0391 Land Rover Palm Beach
FA197258	0273 Land Rover Frisco	FA198032	0391 Land Rover Palm Beach
FA197375	0273 Land Rover Frisco	FA504796	0391 Land Rover Palm Beach
FA197097	0285 Land Rover Larchmont/New Rochelle	FA197317	0393 Land Rover Columbia
FA504977	0285 Land Rover Larchmont/New Rochelle	FA197163	0395 Land Rover Jacksonville
FA197220	0296 Land Rover Tysons Corner	FA197618	0395 Land Rover Jacksonville
FA197903	0303 Land Rover Shreveport	FA197139	0396 Land Rover Manhattan
FA197900	0305 Land Rover Baton Rouge		