

Reference	SSM72071
Models	LR3 / L319 LR4 / L319 Range Rover Sport / L320
Title	Discovery 3/4 LR3/4 & Range Rover Sport (LS) Window Regulator Diagnostic's
Category	Body
Last modified	12-Nov-2014 00:00:00
Symptom	102000 Window/Glass
Attachments	

ContentIssue:

Customers / Dealers may report a concern with the operation of the Front or Rear Window Regulators

Cause:

Various conditions that contribute to the operation of the Window regulator not operating

Action:

The diagnostic's for determining why the Window regulator will not operate & resolution have been updated and can be found in TOPIX Discovery 3 /4 LR3/4 & Range Rover Sport (LS), 501-11 Glass Frames & Mechanisms, Diagnostic's & Testing. It is important that Window Regulators are not replaced (If needed) until diagnostic's have been fully completed

Ratings:

Technicians - Please score the SSM and provide feedback if you scored it 1 - 3 stars.

1 = Poor – Basic information provided – The SSM does not help me resolve the customer concern.

3 = Average – Adequate information provided – The SSM partially helps me resolve the customer concern.

5 = Excellent – All required information provided to resolve the customer concern.