

Reference	SSM72080
Models	Range Rover Sport / L494 Range Rover / L405
Title	L405/L494 – Differential Pinion Oil Seal kits Now Available
Category	Driveline
Last modified	17-Nov-2014 00:00:00
Symptom	509000 Axle Concerns
Attachments	Pinion Oil Seal Kit.pdf
Content	<p><u>Issue:</u> Differential pinion oil seal leak.</p> <p><u>Cause:</u> Pinion seal previously not available as a serviceable component leading to differential replacements.</p> <p><u>Action:</u> Front and rear differential pinion oil seal kits are now available via service parts. Differential replacement is no longer required for leaks associated to the pinion oil seal.</p> <p><u>Part numbers</u> Front Differential Pinion Oil Seal Kit - LR067897 Rear Differential Pinion Oil Seal Kit - LR068951</p> <p>Attached file shows an example of the rear differential oil seal kit contents (front similar).</p> <p><u>For repair procedure please refer to TOPIx as follows -</u> 205-03: Front Drive Axle/Differential - Removal and Installation - Drive Pinion Seal 205-02: Rear Drive Axle/Differential - Removal and Installation - Drive Pinion Seal</p> <p><u>Ratings:</u> Technicians - Please score the SSM and provide feedback if you scored it 1 - 3 stars. 1 = Poor – Basic information provided – The SSM does not help me resolve the customer concern. 3 = Average – Adequate information provided – The SSM partially helps me resolve the customer concern. 5 = Excellent – All required information provided to resolve the customer concern.</p>

