



ACURA

AUTOMOBILE DIVISION

American Honda Motor Co., Inc.
1919 Torrance Blvd., - P.O. Box 2215
Torrance, CA 90509-9870

CSC-10058833-6654

VEHICLE IDENTIFICATION NUMBER: XXXXXXXXXXXXXXXXXXXX

PLEASE DELIVER TO REGISTERED OWNER



JQ8

T17 **AUTOMIXED AADC 296 PL1 R

D1-0006614



▼ PLEASE DETACH, SIGN BELOW AND PLACE IN RETURN ENVELOPE ▼

INFORMATION CHANGE CARD

PLEASE PROVIDE NAME AND ADDRESS CORRECTIONS ON THE REVERSE SIDE

XXXXXXXXXXXXXXXXXXXX

◀ VEHICLE IDENTIFICATION NUMBER

JQ8



PLEASE SIGN AND RETURN THIS CARD ONLY IF YOU HAVE MADE CHANGES

AHA001 0006614

I no longer own this vehicle. It was:

- Sold (*print name and address of new owner on reverse, if known*)
- Exported
- Destroyed
- Stolen
- Lease expired, vehicle returned.
- Other:

Nota:

Si usted necesita esta información en español por favor comuníquese con Relaciones con el Cliente Acura al 1-800-382-2238, y seleccione la opción 4.

Signature: **X** _____ Date: _____

SIGNATURE OF REGISTERED OWNER OR LESSEE REQUIRED

INFORMATION CHANGE CARD

- New owner information
- My name or address has changed

--	--

FIRST NAME

INITIAL

--	--

LAST NAME

--	--

ADDRESS NUMBER

--	--

CITY

--	--

STATE

--	--

ZIP

--	--

EMAIL ADDRESS

--	--	--	--	--

PHONE



ACURA

AUTOMOBILE DIVISION

American Honda Motor Co., Inc.
1919 Torrance Blvd. – PO. Box 2215
Torrance, CA 90509-9870

September 2015

Product Update: Software Update is Required

VIN: XXXXXXXXXXXXXXXXXXXX

Dear _____ :

This letter is to inform you that on certain 2015 TLX vehicles, the vehicle's PCM software does not meet OBDII regulations.

What should you do?

Please contact any authorized Acura dealer for an appointment to have the software updated. Please plan to leave your vehicle at the dealer for one half day to allow them flexibility in scheduling. *This work will be done free of charge.*

California Owners Only

The DMV will not renew your registration until this update has been completed. After the repair procedure, the dealer needs to give you a Vehicle Emission Recall Proof of Correction Certificate. Please make sure the dealer completes and gives you this certificate. Keep this certificate for your records and submit to DMV only if requested by them.

Lessor Information

Please forward a copy of this notice to the lessee.

What to do if you feel this notice is in error

Our records show that you are the current owner or lessee of a 2015 TLX involved in this product update. If this is not the case, or the name/address information is not correct, please fill out and return the enclosed, postage-paid Information Change Card. We will then update our records.

If you have questions

If you have any questions about this notice, or need assistance with locating an Acura dealer, please call Acura Automobile Client Relations at 1-800-382-2238, option 4. You can also locate a dealer online at *Acura.com*.

Sincerely,

**American Honda Motor Co., Inc.
Acura Automobile Division**

Septiembre del 2015

Actualización de producto: Se requiere la actualización del programa

VIN: xxxxxxxxxxxxxxxxxxxx

Estimado _____ :

Esta carta es para informarle que en ciertos vehículos TLX 2015, el programa PCM del vehículo no cumple con los reglamentos OBDII.

¿Qué debe hacer?

Por favor comuníquese con cualquier concesionario Acura autorizado para coordinar una cita para actualizar el programa. Por favor haga planes para dejar su vehículo en el concesionario por medio día, para permitir flexibilidad en la programación. *Este trabajo se realizará sin costo alguno.*

Solamente propietarios en California

El DMV no renovará su registro hasta que esta actualización haya sido completada. Después de completar el procedimiento de reparación, el concesionario necesita entregarle un certificado de Prueba de Corrección – Campaña de seguridad de emisiones del vehículo (Vehicle Emission Recall Proof of Correction Certificate). Por favor asegúrese que el concesionario complete y le entregue este certificado. Mantenga este certificado para sus registros y envíe el certificado para el DMV solamente si el DMV lo solicita.

Información para el arrendador

Por favor envíe una copia de esta notificación al arrendador.

Qué debe hacer si considera que esta notificación es errónea

Nuestros registros muestran que usted es el propietario o arrendador actual de un vehículo TLX 2015 el cual forma parte de esta actualización de producto. Si no es el caso, o si la información de nombre/dirección no está correcta, por favor llene y devuelva la Tarjeta de Cambio de Información anexa con el porte pagado. Con esto actualizaremos nuestros registros.

Si tiene preguntas

Si tiene preguntas acerca de ésta notificación o si necesita asistencia para ponerse en contacto con un concesionario Acura, comuníquese con Relaciones con el Cliente de automóviles Acura al 1-800-382-2238 y seleccione la opción 4. Usted también puede ubicar un concesionario en línea en Acura.com.

Atentamente,

**American Honda Motor Co., Inc.
División Automotriz de Acura**