



TECH TIP: Buzzing Noise from Dash


NUMBER: TT065

MODEL: 2011~12MY Optima (TF/QF)

DATE: 05/14/2015

Symptom: Buzzing noise coming from dash area.

Repair: Operate the air-temp controls or the vent air position control setting. If the noise stops after adjusting the controls, the noise may be caused by a faulty air temp actuator or air vent position actuator. To resolve this concern, identify which blend actuator is the source of the noise (see image) and replace it.



Note: Tech Tips are not a substitute for proper diagnosis.