

SERVICE ADVISORY # 15-227**Summerland Mini Fuse**

It has been determined the below listed vehicles were manufactured with an undersized 15 amp fuse placed in the battery charging circuit which should have a 30 amp fuse. The circuit is wired and rated for 30 amp capacity. This advisory explains how to correct.

Model and Serial Numbers Included: 2015 Summerland Mini 1400FD, 1600BH, 1700FQ, 1800BH

Serial Number Range: F3151065 – F3151779

Parts Required per Unit: (1) 30 Amp Blade Fuse - Acquire locally

Tools Required: - Ink Pen

ONE INSPECTION and REPAIR

Step 1 Locate the trailer on a level, flat and hard surface. Chock the wheels.

Step 2 Locate the fuse panel in the unit. Remove the 15 amp fuse from the number 6 location of the fuse panel. Replace the fuse with a 30 amp fuse. Change the noted fuse size of position 6 on the information label from 15 to 30.




Fig. 1




Fig. 2

TWO WARRANTY REIMBURSEMENT

Submit the request on Key Express using **Flat Rate Code # 7122742B** with **Service Advisory #15-227** noted in the customer complaint section. The time authorized for this repair is **.2 hours**.

If you have any questions, please call Customer Service at **(866) 273 - 1452**