



RECREATIONAL VEHICLE SERVICE CAMPAIGN

September 4, 2015

SERVICE ADVISORY 15-236

«Dealer_Name»
ATTN: Service Manager
«Street»
«City», «State» «Zip»
«Country»

Dear «Dealer_Name»,

Reason for this campaign

It has been determined that some 2016 Denali 280LBS models were built with improper refrigerator ventilation. A divider panel must be cut out to allow air flow through the refrigerator cabinet.

The campaign population includes:

2016 Denali 280LBS Fifth Wheels in the Serial Number Range GP940117 – GP940448

Our records indicate unit(s) sold or in your present lot inventory fall within this range, which will require inspection. **Important:** Please complete the service campaign on these units before retail delivery. Our records indicate the following unit serial number(s) are presently in your inventory or have been sold:

«VIN1»	«VIN2»	«VIN3»	«VIN4»	«VIN5»
--------	--------	--------	--------	--------

-- Serial numbers with '*' have been retail sold --

We apologize for any inconvenience this situation may cause and greatly appreciate your cooperation. Should you have any questions or concerns regarding this correspondence or the attached Service Advisory, please contact us at: **(855) 382-4100**

Sincerely,

KEYSTONE RV COMPANY

Rick Deisler
Sales & Service Manager

PO Box 2000 Goshen, IN 46527-2000
Phone: (574) 535-2100 – Fax: (574) 535-2199
www.keystonerv.com