

[Next Unread Message](#)[View Message](#)

Sent on	12	22	2015	Expires on	03	21	2016
---------	----	----	------	------------	----	----	------

From	Campaign Administration
------	-------------------------

Subject	Product Update: 2015-16 Fit and 2016 HR-V Door Handle Bracket
---------	---

DATE: December 22, 2015

TO: All Honda Sales, Service &amp; Parts Managers and Personnel

FROM: Campaign Administration

Re: Product Update: 2015–16 Fit and 2016 HR-V Door Handle Bracket

Today, December 22, 2015, American Honda Motor Co., Inc. is announcing two product updates for 84,138 units of the 2015-16 Fit & 16,019 units of the 2016 HR-V vehicles to inspect the inner door handle brackets for corrosion.

**Basic Problem**

Non-galvanized door handle brackets were installed in the occupant doors during manufacturing and may be susceptible to corrosion. The Fit model has all occupants' doors (four) affected; the HR-V model only has the front passenger side door affected.

**The Repair**

Inspect the respective occupant's inner door for corrosion around the door handle, and if found, repair and protect the door from further corrosion. Replace door handle brackets with new countermeasure parts and protect for corrosion.

**Service Bulletin**

Service bulletins 15-088, *Product Update: 2015–16 Fit Door Handle Bracket* and 15-090, *Product Update: 2016 HR-V Front Passenger's Door Handle Bracket* have been posted to the Service Information System today in support of this campaign. It includes parts, warranty and repair procedure information related to this product update.

**Parts Information**

For the HR-V repair, required part 06721-T7W-A00 will be available through controlled parts order; a valid, affected VIN will be required to obtain a door handle bracket kit. Some repairs, for both Fit and HR-V, will require a rust remover. One can of 08732-9020, which can repair 35 vehicles, has been allocated to every dealer. This part is now being controlled and if you require an additional can, you will need to contact your facing Part Center to request a part.

**Client Notification**

American Honda expects to notify owners of affected vehicles by the end of January 2016.

As always, please make sure to check iN VIN status to determine if a particular vehicle is eligible for this product update.

Click [here](#) for a copy of 15-088

Click [here](#) for a copy of 15-090