

[Next Unread Message](#)[View Message](#)

Sent on	10	23	2015	Expires on	11	06	2015
From	Motorcycle National Field Service						
Subject	Safety Recall: 2001-2015 GL1800/A, GL1800B/BD Service Bulletin Published						



Motorcycle National Field Service

October 23, 2015

Service Bulletin: 2001-2015 GL1800/A, GL1800B/BD Secondary Master Cylinder Replacement

Dear Honda Powersports Dealer:

The Service Bulletin in support of the SAFETY RECALL of 2001-2015 GL1800/A and GL1800B/BD motorcycles for a potentially defective Secondary Master Cylinder is posted on *IN*.

SERVICE BULLETIN

SAFETY RECALL: GL1800 #23 includes the affected models, repair procedure, parts information, as well as warranty claim information.

CUSTOMER NOTIFICATION

AHM intends to mail customer letters during the month of November, 2015 based on vehicle registration information and regulatory agency approvals.

PARTS INFORMATION

Initially, parts will be allocated to your dealership based upon your affected inventory. Later, parts will be available on open order.

Make sure all departments in your dealership are aware of this action.

If you have any questions, please contact Motorcycle TechLine at (800) 421-1900, Option 9; through *TechLine Connect* on *IN*; or contact your District Service Manager.

Sincerely,

American Honda Motor Co., Inc.**Bradley Little**

Manager, National Field Service
Motorcycle Division

Bulletin Number: 15-0294

