

2015 Fit Plug Top Coil Safety Recall Q&A	
What is the reason for this recall?	The plug top ignition coils may degrade over time, which, in the worst case, could cause the vehicle's engine to stall, potentially increasing the risk of a crash.
Why are the noise suppression capacitors degrading?	The original plug top ignition coil design can allow some unintended electrical discharge between the electrode and the winding wire in the capacitor. This electrical discharge can, over time, cause corrosion of the winding wire that could lead to its disconnection and melting.
How could this degradation lead to vehicle stalling?	This degradation could lead to two primary symptoms. First, the output from the ignition coil may drop low enough to cause the vehicle's Malfunction Indicator Lamp (aka the Check Engine Light) to illuminate. This is the most common scenario. Second, excess electrical noise caused by the degradation could interfere with the electronic fuel injection system, which could result in the engine stalling.
What will be done to recalled vehicles?	A Honda dealer will replace the four plug top ignition coils, free of charge. Additionally, if any surface level electrical corrosion resulting from this condition is found on a corresponding spark plug, it will be cleaned as part of this repair.
How long will the inspection/repair take?	Customers should ask their dealers for a total time estimate when making an appointment, as each dealer's daily schedule is different.
When will customers be notified?	Owners can check their vehicle recall status now at www.recalls.honda.com . Letters to owners of affected 2015 Fit vehicles will be mailed starting on October 6, 2015.
What should a customer do if their vehicle is experiencing a problem now?	All of these vehicles are eligible for the recall repair immediately. If a customer's vehicle is included in the recall, they should contact a Honda dealer as soon as possible to schedule repair. If the vehicle is not included in the recall or is experiencing another issue, a Honda dealer can assist with diagnosis and repair. This recall only applies to a limited number of vehicles, and it is unnecessary for all owners of all 2015 Fit vehicles to visit a dealer. However, we want each customer with an included vehicle to ensure that it is repaired.
Are all 2015 Fits part of this recall?	No. Only a limited number of specific vehicles are affected by this recall. Only certain 2015 Fit vehicles made during a specific production period are affected.
Is there a potential to include other vehicles in the future?	We are confident that we have identified all of the potentially affected vehicles and do not expect to add any in the future.
Where were these vehicles built?	Celaya, Mexico.
How many vehicles are affected by this recall?	17,796