

Reference	SSM71862
Models	Defender / L316 Discovery Sport / L550 LR2 / L359 LR3 / L319 LR4 / L319 Range Rover / L322 Range Rover / L405 Range Rover Evoque / L538 Range Rover Sport / L320 Range Rover Sport / L494
Title	Instrument Pack Lower level Assembly Lens Replacement
Category	Body
Last modified	11-Feb-2015 00:00:00
Symptom	107000 Interior Trim
Content	<p>Issue: Customer complains of damage/markings on the surface of the vehicle's instrument pack lens.</p> <p>Cause: Damage/markings caused by object impact against the lens. Staining/discoloration contamination caused by using any type of cleaning product on lens. Important: Owners Handbook specifies to clean with a lightly moistened cloth and do not use chemical agents or domestic cleaners</p> <p>Action Where a customer concern is reported, please order the Lens Kit for the relevant model</p> <p>Part Number Model LR038299 – L316 7A732615 Onwards; L319 5A000259-9A513325; L320 5A900109-9A215622 LR041042 – L319 AA513326 Onwards; L320 AA215623 Onwards LR048407 - L359 7H000201-CH321214 LR070792 - L539 DH321215 Onwards LR048302 – L538 CA600000 Onwards; L550 H501001 Onwards LR048302 – L494 EA300001 Onwards – Low Line Instrument Pack LR059859 – L405 13/14MY DA100001 – A130415 – High Line + No side Clips LR063634 - L405 14MY 130416 onwards - High Line + side clips</p> <p>Please refer to Topix Procedure: Service; Workshop Information; Workshop Manual; Workshop manual Vehicle Model, 4: Electrical; 413: Instrumentation and Warning Systems; 413-01 Instrument Cluster; Removal and Installation - Instrument Cluster Lens.</p> <p>Note: Any marks or damage identified following PDI on all the listed vehicle model lines are not covered by warranty. Range Rover L322 does not have service replacement Instrument Pack lens and the lens cleaning instruction should be followed for any marks identified in the first instance.</p>