

<b>Reference</b>	SSM72167
<b>Models</b>	Range Rover Evoque / L538
<b>Title</b>	Front Radiator Grille Poor Cosmetic Appearance
<b>Category</b>	Body
<b>Last modified</b>	02-Feb-2015 00:00:00
<b>Symptom</b>	108000 Ext. Trim/Accessories

**Content****Issue**

Customer reports of poor appearance of the front radiator grill in the form of peeling, fading, and/or discolouration.

**Cause**

The clear lacquer coating on the grille not correct to manufacturing standard.

**Action**

The manufacturing process has now been improved and quality checks added to ensure that the clear coating is now of an improved standard, the assured VIN for vehicles fitted with the improved standard Grille is **H024935**

In addition to the above assured VIN new parts of the assured standard are now in service stocks from 30/1/15.

**JLR engineering would like to thank everyone who submitted EPQR's highlighting and assisting this investigation. Please only submit further EPQR's for vehicles manufactured after the assured VIN of H024935 or for vehicles that have new parts fitted that were ordered and supplied after the 30/1/15 that have failed again.**