

NEWMAR CORPORATION WARRANTY DEPARTMENT

TECHNICAL SERVICE BULLETIN

DATE ISSUED	MODEL YEAR(S) AFFECTED	TSB #
04/10/2015	2014-2015	Recall 15V-149 TSB 416

BRAND

Bay Star Sport	<input type="checkbox"/>	Ventana	<input type="checkbox"/>	Essex	<input checked="" type="checkbox"/>
Bay Star	<input type="checkbox"/>	Dutch Star	<input type="checkbox"/>	King Aire	<input checked="" type="checkbox"/>
Canyon Star	<input type="checkbox"/>	Mountain Aire	<input checked="" type="checkbox"/>	Other	<input type="checkbox"/>
Ventana LE	<input type="checkbox"/>	London Aire	<input checked="" type="checkbox"/>		

DESCRIPTION

This notice is sent to you as a Newmar Dealer in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Newmar Corporation has decided that a defect which relates to motor vehicle safety exists in specific motor homes.

AM Equipment Frameless style windshield wiper blades P/N 302-2320 supplied for Newmar coaches may separate from wiper arm connector when wiper system is operated at the high speed setting. If the wiper system fails, the operator will have reduced visibility which could result in a crash.

Motorhomes included in this recall include:

King Aire, Essex, London Aire and Mountain Aire motorhomes built between 11/26/2013 and 11/11/2014.

These motor homes require immediate service. Continued use poses a potential safety hazard.

RECOMMENDED ACTION

DEALER CAMPAIGN RESPONSIBILITY

Dealers are to provide to all customers/owner vehicles the service of completing this campaign at no charge to the customer/owner regardless of vehicle age, vehicle mileage, or ownership at the time of repair.

REPAIR PROCEDURE

Please reference AM Equipment work instructions enclosed.

If you should have any questions please contact the Newmar service department at: 1-866-290-5371.

US NHTSA# 15V-149
CAN Recall # 2015-108

Flat Rate code – 15V-149
Labor Time – replace 0.1 hrs ea.
P/N #302-1320

Please read this bulletin in its entirety prior to beginning any diagnosis or repairs.



EQUIPMENT

Technical Service Bulletin

Notice of wiper blade replacement requirement

To: Newmar Corporation and Dealer Network
From: AM Equipment
Date: 2/19/2015


This bulletin describes a required wiper blade replacement on the specific 2014 and 2015 model year Newmar coaches listed in this bulletin

Frameless style windshield wiper blades P/N 302-2320 supplied on designated coaches may separate from wiper arm connector when wiper system is operated at the high speed setting.

Frameless wiper blades P/N 302-2320 MUST be immediately replaced with framed wiper blades P/N 302-1320 supplied with this service bulletin.

To comply with this service bulletin;

1. Remove frameless blade 302-2320 from wiper arm, driver and passenger side.
DISPOSE OF REMOVED BLADES



To Remove Frameless Blade

1. Lift plastic cover to expose arm hook.
2. Squeeze plastic clip
3. Push blade back to remove from arm




2. Install framed blade 302-1320 on wiper arm, driver and passenger side.



To Install Framed Blade

- 1 Orient the plastic retainer to the locking nib faces the down towards the glass
- 2 Slide hook of arm around blade plastic retainer
- 3 "CLICK" blade into place. **Test to insure blades has locked onto the hook securely**
- 4 Remove protective from rubber part of blade



AM Equipment Technical Service Line – 541-327-1546
PO Box 790, 402 E. Hazel Jefferson Oregon 97352
www.amequipment.com

Vehicles affected by this bulletin

Product ID	Year	Brand	Type	Model	Product ID	Year	Brand	Type	Model
501121	2015	LA	DP	4553	530287	2015	KG	DB	4599
501124	2015	LA	DP	4553	530288	2015	KG	DB	4553
501125	2015	LA	DP	4553	530289	2015	KG	DB	4553
501126	2015	LA	DP	4553	530290	2015	KG	DB	4503
501127	2015	LA	DP	4553	530291	2015	KG	DB	4553
501128	2015	LA	DP	4553	801095	2014	EX	DP	4553
501129	2015	LA	DP	4553	801098	2015	EX	DP	4544
501130	2015	LA	DP	4553	801099	2015	EX	DP	4553
501132	2015	LA	DP	4503	801100	2015	EX	DP	4508
501133	2015	LA	DP	4503	801101	2015	EX	DP	4553
501134	2015	LA	DP	4503	801102	2015	EX	DP	4503
501135	2015	LA	DP	4553	801103	2015	EX	DP	4553
501136	2015	LA	DP	4553	801104	2015	EX	DP	4553
501137	2015	LA	DP	4553	801105	2015	EX	DP	4503
501138	2015	LA	DP	4553	801106	2015	EX	DP	4553
501139	2015	LA	DP	4553	801107	2015	EX	DP	4503
501140	2015	LA	DP	4553	801108	2015	EX	DP	4503
501141	2015	LA	DP	4553	801109	2015	EX	DP	4553
501142	2015	LA	DP	4503	801110	2015	EX	DP	4503
501143	2015	LA	DP	4553	801111	2015	EX	DP	4553
501144	2015	LA	DP	4553	801112	2015	EX	DP	4553
501145	2015	LA	DP	4553	801113	2015	EX	DP	4553
501146	2015	LA	DP	4553	801114	2015	EX	DP	4553
501147	2015	LA	DP	4553	801115	2015	EX	DP	4503
501148	2015	LA	DP	4503	801116	2015	EX	DP	4553
501149	2015	LA	DP	4553	801117	2015	EX	DP	4553
501150	2015	LA	DP	4553	801118	2015	EX	DP	4553
501151	2015	LA	DP	4503	801120	2015	EX	DP	4553
501152	2015	LA	DP	4553	801121	2015	EX	DP	4553
501154	2015	LA	DP	4599	801122	2015	EX	DP	4553
501155	2015	LA	DP	4503	801123	2015	EX	DP	4503
501156	2015	LA	DP	4553	801124	2015	EX	DP	4553
501157	2015	LA	DP	4553	801125	2015	EX	DP	4553
501158	2015	LA	DP	4553	801127	2015	EX	DP	4503
501158	2015	LA	DP	4553	801128	2015	EX	DP	4553
501159	2015	LA	DP	4503	801129	2015	EX	DP	4503
501160	2015	LA	DP	4553	801130	2015	EX	DP	4503
501163	2015	LA	DP	4553	801132	2015	EX	DP	4503
501164	2015	LA	DP	4503	801133	2015	EX	DP	4503

CONTINUED

Product ID	Year	Brand	Type	Model	Product ID	Year	Brand	Type	Model
501168	2015	LA	DP	4553	801134	2015	EX	DP	4553
501170	2015	LA	DP	4599	801135	2015	EX	DP	4553
501172	2015	LA	DP	4503	904245	2015	MA	DP	4501
501173	2015	LA	DP	4553	904266	2015	MA	DP	4369
501174	2015	LA	DP	4553	904267	2015	MA	DP	4503
501175	2015	LA	DP	4503	904268	2015	MA	DP	4553
501177	2015	LA	DP	4553	904269	2015	MA	DP	4553
501178	2015	LA	DP	4553	904270	2015	MA	DP	4553
501179	2015	LA	DP	4553	904271	2015	MA	DP	4503
501180	2015	LA	DP	4553	904273	2015	MA	DP	4553
501181	2015	LA	DP	4553	904274	2015	MA	DP	4503
501181	2015	LA	DP	4503	904275	2015	MA	DP	4553
501182	2015	LA	DP	4599	904276	2015	MA	DP	4553
501183	2015	LA	DP	4553	904277	2015	MA	DP	4503
501184	2015	LA	DP	4553	904278	2015	MA	DP	4553
501185	2015	LA	DP	4553	904279	2015	MA	DP	4553
501186	2015	LA	DP	4503	904280	2015	MA	DP	4553
501187	2015	LA	DP	4553	904281	2015	MA	DP	4553
501191	2015	LA	DP	4553	904282	2015	MA	DP	4503
501192	2015	LA	DP	4553	904284	2015	MA	DP	4503
501205	2015	LA	DP	4553	904285	2015	MA	DP	4553
530232	2015	KG	DB	4553	904286	2015	MA	DP	4553
530257	2015	KG	DB	4593	904287	2015	MA	DP	4503
530258	2015	KG	DB	4593	904288	2015	MA	DP	4553
530261	2015	KG	DB	4593	904288	2015	MA	DP	4503
530263	2015	KG	DB	4593	904289	2015	MA	DP	4553
530264	2015	KG	DB	4593	904291	2015	MA	DP	4553
530265	2015	KG	DB	4584	904292	2015	MA	DP	4503
530266	2015	KG	DB	4599	904293	2015	MA	DP	4503
530267	2015	KG	DB	4584	904294	2015	MA	DP	4553
530268	2015	KG	DB	4553	904295	2015	MA	DP	4503
530269	2015	KG	DB	4553	904297	2015	MA	DP	4553
530270	2015	KG	DB	4553	904299	2015	MA	DP	4553
530271	2015	KG	DB	4503	904300	2015	MA	DP	4503
530272	2015	KG	DB	4553	904302	2015	MA	DP	4503
530273	2015	KG	DB	4553	904303	2015	MA	DP	4553
530274	2015	KG	DB	4503	904305	2015	MA	DP	4553
530275	2015	KG	DB	4503	904306	2015	MA	DP	4503
530276	2015	KG	DB	4553	904307	2015	MA	DP	4553
530277	2015	KG	DB	4553	904309	2015	MA	DP	4568

CONTINUED

Product ID	Year	Brand	Type	Model		Product ID	Year	Brand	Type	Model
530278	2015	KG	DB	4503		904311	2015	MA	DP	4553
530279	2015	KG	DB	4553		904312	2015	MA	DP	4503
530280	2015	KG	DB	4553		904313	2015	MA	DP	4553
530281	2015	KG	DB	4553		904314	2015	MA	DP	4553
530282	2015	KG	DB	4553		904315	2015	MA	DP	4568
530283	2015	KG	DB	4553		904316	2015	MA	DP	4553
530284	2015	KG	DB	4553		904317	2015	MA	DP	4553
530285	2015	KG	DB	4553		904318	2015	MA	DP	4568
530285	2015	KG	DB	4503		904319	2015	MA	DP	4503
X	X	X	X	X		904331	2015	MA	DP	4553

END