



Service Bulletin


PRELIMINARY INFORMATION

Subject: Information on Missing A/C Refrigerant Charge Label on Replacement Front Compartment Front Sight Shield

Models: 2013-2014 XTS
Equipped with RPO LFX or LF3
Vehicles Built Prior to September 16, 2013

Attention: This PI also applies to any of the above models that may be Middle East and China Export vehicles.

Some technicians may notice during replacement of the front compartment front sight shield that there is no A/C Refrigerant Charge label affixed to the replacement part.



1. Old Label

2. New Label


This is due to the new service part not including the A/C Refrigerant Charge Label as shown above.

If replacing the front compartment front sight shield, follow the information below to obtain and relocate the correct A/C Refrigerant Charge label.

Affixing New A/C Refrigerant Charge Label

The new A/C Refrigerant Charge label will be installed on the right inner side of the hood of the vehicle.

Note: Be sure to apply the correct label per application.



Install the label 1½ inches (38 mm) parallel to the right hood hinge in between the two rivets like shown above.

Parts Information

Part Number	Description
20988811	(R-1234yf) LABEL-A/C REFRIG CHRГ
20988810	(R-134a) LABEL-A/C REFRIG CHRГ

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION