



Bulletin No.: PIE0319A

Date: Jun-2015

# Service Bulletin

## PRELIMINARY INFORMATION

**Subject:** Engineering Information – Fluid Leak from Front End of Allison Transmission

**Models:** 2014-2015 Chevrolet Silverado 2500/3500

2014-2015 GMC Sierra 2500/3500

***This PI has been revised to end the need for information from the field. Please discard PIE0319.***

If you encounter a vehicle with this concern, please contact TAC for additional information.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION