



Service Bulletin

PRELIMINARY INFORMATION

Subject: PQC Part Restriction CTS AISIN TL80SN 8 Speed Transmission Assembly Torque Converter Valve Body And TCM Part Restriction Has Ended

Models: 2014-2015 Cadillac CTS Sedan
Equipped with AISIN TL80SN 8 Speed (MGG) Transmission

This PI was superseded to add notice that the PQC part restriction has ended. Please discard PIP5144C.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

The PQC Parts Restriction has ended on the on the TL80SN 8 Speed (MGG) Transmission Assembly, Torque Converter, Valve Body and Transmission Control Module (TCM).

Recommendation/Instructions

Parts can now be ordered through the regular CCA parts process

Your cooperation with this program was greatly appreciated.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION