



Service Bulletin

PRELIMINARY INFORMATION

Subject: Normal Operating Characteristics And Diagnostic Tips For The CVT7 Transmission

Models: 2014-2015 Chevrolet Spark

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

Some customers may comment on the operation or performance of the CVT7 transmission.

Recommendation/Instructions

Please refer to the following normal operating characteristics of the CVT7 transmission before attempting any diagnostics or repairs to the engine or transmission on this vehicle.

When the transmission is at operating temperature torque converter lockup can occur as low as 8 mph and the range for lockup is 8-18mph depending on the throttle angle

CVT transmissions are usually thought of as a no shift transmission however the CVT7 transmission has a high and low range made possible by the use of two clutch packs and one planetary gear set.

The input torque into these clutches and planetary gear set comes from the drive belt and pulleys.

The torque converter clutch locking up or releasing may also feel like a shift to the customer.

While in low range the RPM of the engine may sound loud at low speed operation (5-15 mph) because there is not enough road noise to cancel it out.

While in high range at the same engine RPM the road noise will cancel out the engine noise due to the increase in vehicle speed. (50-60 mph).

The TCM is programmed to simulate a step transmission upshift (Saw tooth simulated shift) on moderate to hard acceleration. This feature is built into the calibration and cannot be changed.

Please refer to latest version of PI1247 normal operation for the CVT7 during cold operation. High range pulley ratio is locked out until the transmission fluid reaches normal operating temperature. This is done to help the fluid heat up faster. Torque converter lockup may also be inhibited.

For 2014 model year vehicles with low power at a launch, shudder, shift or engagement into gear concerns make sure that the TCM calibration is up to date per the latest version of PI1309.

The 2015 model year vehicles already have the updated calibration installed at the factory.

For transmission slipping or high engine rpm concerns with P0885 setting refer to the latest version of PI1053.

The transmission may stay in high range gear during a rolling stop or complete stop even after the latest TCM calibration update is installed to avoid a bump fee at a stop or a launch.

The amount of throttle required to cause a shift into low range is much less after the TCM calibration update for the 2014 model year vehicles.

During a light throttle launch the transmission may stay in high range.

Anytime a DTC is set in the TCM check for a damaged TCM cover.

Many engine and transmission DTCs will cause the transmission to go into limp mode.

While in limp home mode the transmission pulley and gear ratios may be locked. Torque converter lockup may be disabled. Engine torque will be limited to various amounts.

Some DTCs will cause pressure control system to request maximum line pressure which will cause a whine noise from the transmission fluid pump.

For other noise concerns refer to the latest version of PIP5275.

The latest version of PIP5283 shows the pin location of the transmission pass thru connector.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION