



# Service Bulletin

File in Section: -

Bulletin No.: PIC6084

Date: April, 2015

## PRELIMINARY INFORMATION

**Subject:** Tire Replacement / Mounting Information

**Models:** 2015 Chevrolet Corvette Z06

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

### Condition/Concern

Some dealership technicians may have difficulty seating the beads on any of the various tires available on the 2015 Corvette Z06.

### Recommendation/Instructions

this issue is encountered and a dealership is unable to safely mount a tire onto a wheel, please call the General Motors Technical Assistance Center (TAC) for additional information on completing this service procedure.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.