



Service Bulletin

PRELIMINARY INFORMATION

Subject: PQC Parts Restriction has ended On 2014 and 2015 Chevrolet Camaro Equipped With RPO Z28

Models: 2014 and 2015 Chevrolet Camaro equipped with RPO Z28

This PI was superseded to update Part Information. Please discard PIC5983F.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

PQC Parts Restriction has ended on 2014 and 2015 Chevrolet Camaro Equipped With RPO Z28

Recommendation/Instructions

Parts for a 2014 or 2015 Chevrolet Camaro equipped with RPO Z28 can now be ordered through the regular CCA parts process.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION