



Service Bulletin

PRELIMINARY INFORMATION

Subject: SES Lamp With Camshaft Actuator Codes After SI Diagnosis Have Been Followed

Models: 2007 - 2015 Cadillac Escalade, Escalade Hybrid
 2007 - 2015 Chevrolet Avalanche, Corvette, Express, Silverado, Silverado Hybrid, Suburban, Tahoe, Tahoe Hybrid
 2007 - 2015 GMC Savana, Sierra, Sierra Hybrid, Yukon, Yukon Hybrid
 With V-8 engine
 4.8L L20
 5.3L L83 LC9 LMF LMG
 6.0 L76 L77 L96 L99 LC8 LY6 LZ1
 6.2 L9H L86 L92 LT1 LT4

This PI was superseded to update Model Years and Engine RPO Codes. Please discard PIP5258.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

A vehicle may be brought to the dealer with an SES lamp with P0011 setting.

If SI has been followed without a fix the following information may be help full

Recommendation/Instructions

If the SI flow chart has been followed and it did not isolate the concern.

1. Check the oil pressure at the oil pressure sender.
2. Check the number 2 cam bearing. (This is the location the oil is feed from to the actuator).

Warranty Information

For vehicles repaired under warranty use:

Labor Operation	Description	Labor Time
4064690	Camshaft Replacement	Use Published Labor Operation Time

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION