



# Service Bulletin

## PRELIMINARY INFORMATION

**Subject:** Diagnostic Tip - Radio Does Not Show The Correct Song Information When Using An iPod

**Models:** 2015 Buick LaCrosse, Regal  
2015 Cadillac ATS, CTS, SRX, XTS  
2015 Cadillac Escalade Models (RPO AVF\*)  
2015 Chevrolet Colorado, Corvette, Impala, Silverado 1500  
2015 Chevrolet, Silverado HD, Suburban, Tahoe (RPO AVF\*)  
2015 GMC Canyon, Sierra 1500  
2015 GMC Sierra HD, Yukon Models (RPO AVF\*)  
\*Only Utilities and HD pickup trucks equipped with RPO AVF  
With Radio RPO's IO4, IO5, and IO6

*This PI was superseded to update Recommendation/Instructions. Please discard PIC6056A.*

### Condition/Concern

A customer may comment that when connecting their iPod to their vehicle and listening to it, the first song will still be displayed on the radio screen even though the next song in the list is actually playing

### Recommendation/Instructions

If this concern is encountered, use the browse button on the radio display and navigate to the desired artist, album, song, or Genre. Once the desired selection is made, the correct information will be displayed on the radio screen.

**Note:** These steps will need to be performed every time that the iPod is disconnected and reconnected.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION