



Tech Tips

TT 87-11-01

Date: March 18, 2011

2011-2015 Jetta, 2012-2014 Beetle – A/C Control Module Basic Settings

July 31, 2015: Update to model year applicability.

After A/C control module J301 is replaced, fault 00898-005 “Activation A/C Compressor No or Incorrect Basic Settings” may be stored. GFF test plan does not perform Activation A/C Compressor Basic Setting. To perform basic setting and resolve this fault, follow steps below:

- Set the blower on position 1 or 2
- Set Airflow direction to “vent”
- Set Temperature to “full cold”
- Start the engine
- Press and hold the defrost and a/c buttons at the same time
- Hold the buttons for 5-7 seconds until the defrost, A/C, and recirc buttons are illuminated
- Restart the vehicle and recheck all functions before returning the vehicle to the customer