

Tech Tips

TT 63-15-01

Date: April 17, 2015

2015 Passat, Golf, Golf Sportwagen- Rear Bumper Cover – Paint Peeling

July 3, 2015: Update to Model Applicability.

There have been cases identified where the paint is chipping/peeling on the rear bumper cover (see picture below). This issue was caused by process deviations at the supplier.



Passat rear bumper cover – affected area

Material recommendation:

In addition to the repair procedure in ELSA we recommend the use of **35887 3M EZ Sand Flexible Parts Repair**. The use of this product will assure the adhesion of the paint. Use **3M 05907 – Polyolefin adhesion promoter** to clean the area before applying the 3M 35887 EZ sand flexible parts repair.



3M 05907 – Polyolefin adhesion promoter
flexible parts repai



3M 35887 – EZ sand