

# Technical Service Bulletin



## 00 VIN plates, Safety Certification labels, ordering procedures

00 15 78 2021205/3 December 10, 2015. Supersedes Technical Service Bulletin Group 00 number 10-05 dated June 14, 2010 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
All	2000 - 2017	All	Not Applicable

## Condition

REVISION HISTORY		
Revision	Date	Purpose
3	-	Revised header data (Added model years)
2	6/14/2010	Revised header data (Added model years)
1	7/23/2009	Original publication

VIN plate and/or B-Pillar Safety Certification label requires replacement.

## Technical Background

Not applicable.

## Production Solution

Not applicable.

## Service

When a new VIN plate or B-Pillar Safety Certification label is required:

1. Save all VIN plates and/or B-Pillar Safety Certification labels removed from vehicle until the new VIN plate or label arrives.
2. On the Access Audi web site, expand either the **Parts** menu or **Service** menu, then select **Compliance Label Ordering Portal**. Log in.
3. Select **VIN Plate/B-Pillar Certification Labels**.
4. Enter your dealer code.
5. Enter the VIN.

# Technical Service Bulletin



6. Enter information from the old VIN plate and/or B-Pillar Safety Certification label (VIN, production date, weights). This information will be required to complete the web-based form.  
The completed web-based form will be electronically routed to your AASM for approval.  
The AASM will take the necessary steps to fulfill the request.  
Once the VIN plate and/or Safety Certification label is received from AG, the AASM will provide the label.

## Warranty

This TSB is informational only and not applicable to any Audi warranty.

## Additional Information

All parts and service references provided in this TSB (2021205) are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.