

Date: Oct-2015

## **Service Bulletin**

## **INFORMATION**

**Subject:** Updated Front Fascia License Plate Bracket Installation Instructions

Attention: This Bulletin also applies to any of the models that may be Export vehicles.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Volt	2016	2016				






The purpose of this Bulletin is to notify dealership personnel that when installing the license plate bracket, the instructions may be misleading regarding the

location for the fascia's center point, which will leave large gaps between the bracket and fascia. Follow the procedure listed below for the proper installation.

## **Service Procedure:**



- 1. BEFORE mounting the bracket, on a solid surface, drill four 5.5 mm (7/32 in) holes at the marked locations on the bracket.
- 2. Align the bracket to the center point on the fascia with the least amount of gap.
- **3.** Using masking tape, mark the position of the left, right and bottom edges.
- 4. While holding the bracket in place, redrill the holes to mark the location on the fascia.
- **5.** Secure the bracket to the fascia with the rivets provided.

**Note:** Install the top two rivets first followed by the bottom two rivets.

Version	1
Modified	

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION