



Service Bulletin

TECHNICAL

Subject: No Start and/or Start Stall

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Cruze	2014	2015			2.0L Diesel (RPO LUZ)	

Condition	Some customers may comment on a no start and/or start stall.
Cause	This condition may be due to the engine exhaust gas recirculation (EGR) valve being stuck open.

Correction

If no codes are set, engine cranks without issue, and the vehicle has adequate fuel pressure, remove and inspect the EGR valve. If stuck open, replace the EGR valve.

Service Procedure:

Refer to *Exhaust Gas Recirculation Valve Replacement* in SI.

Parts Information

Description	Part Number	Qty
VALVE KIT-EGR	55593617	1

Warranty Information

For vehicles repaired under the Emission coverage, use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
4024770	Exhaust Gas Recirculation Valve Replacement	Use Published Labor Operation Time

Version	2
Modified	Nov. 17, 2016 – Updating the coverage statement in the Warranty Information.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION