



Service Bulletin

PRELIMINARY INFORMATION

Subject: Caller ID Unavailable After OnStar Upgrade

Models: 2000-2015 All GM Passenger Car and Light Duty Trucks With OnStar Canada Upgrade

Condition/Concern

The incoming caller ID may no longer be available or displayed after the Canada OnStar upgrade outlined in the latest version of 15-08-44-001 is performed

Recommendation/Instructions

Engineering is aware of the concern and is currently working of a resolution.

Customer Information

Customer Information Please communicate to the customer that we apologize for this inconvenience and that General Motors is working on a solution for this concern. Once a solution is available, this PI will be updated with additional details - allowing dealership personnel to contact the customer to schedule a service appointment and repair the vehicle.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION